



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 19/09/2026

Shift: C

Incharge(s): Amit Roy,K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-22	REPORTED LT NOT TAKING PLACE FOUND M-2 OLR ACTED DUE TO GEAR BOX PROBLEM	RESET DONE AND INFORMED TO MECHANICAL	22:10:00	22:20:00	
2	OHP	CO-26	OLR ACTED (5TIMES)	RESET DONE	23:05:00	05:15:00	
3	OHP	CO-6A	OLR ACTED	RESET DONE	23:45:00	23:55:00	
4	OHP	WOBR ON CO-25	LUFFING NOT TAKING PLACE FOUND DOWN LIMIT ACTED	TEMPRARY LIMIT BYPASSED THAN LUFF UP BY PASS REMOVED	00:20:00	00:35:00	
5	OHP	VS-2	OLR ACTED	RESET DONE	05:00:00	05:10:00	
6	CHP	CC-52	MPD TRIP	RESET DONE	23:45:00	23:50:00	
7	CHP	CC-54	OLR ACTED	RESET DONE	00:10:00	00:20:00	
8	CHP	CC-43	ZSS MODUL PROBLEM	ZSS MODULE REPLACED WITH NEW ONE THAN OK	23:20:00	23:40:00	
9	CHP	SCR-5 ON CC-32	REPORTED LT NOT TAKING PLACE	PCRD NOT ROTATING.CHAIN PROBLEM FROM MECHANICAL SIDE.AFTER MECHANICAL WORK FOUND PCRD CONTACTOR ONE POLE NOT MAKING.BYPASSED AND TESTED OKAY	01:00:00	01:33:00	CONTACT OR TO BE REPLACED