



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 13/09/2026

Area: OHP

Equipment	Job
co-14b bss	chp side switch mechanism failed, switch replaced and restored in circuit.
co-36	mccb replaced with spare one in module and checked.