



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/09/2026

Shift: A

Incharge(s): Amit Roy,K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO-26	Luffing not taking place	Wrong complaint	09:00:00	09:20:00	
2	OHP	CO-84	BRS not resetting	Decksheet jamming.	10:30:00	10:45:00	Informed to operation
3	OHP	CO-26	Reported tripped	OLR acted.Reset done	13:30:00	13:40:00	
4	OHP	CO-34	Reported tripping without fault	Checked after opration demand fulfilled and found control supply ok field wire at I/O rack loose.Tightened	12:30:00	13:00:00	NO delay
5	CHP	CC-52	MPD tripped	Reset done(3 times)	09:00:00	11:50:00	
6	CHP	SCR-9 on CC-104	Slewing not taking place and B/C not running	MCCB tripped.Made on. B/C CS acted	08:45:00	09:20:00	
7	WT	CT-1	Reported tripping immediately on command	D-2 tripping on OCA fault.Motor checked and found one internal winding short circuit.Motor replaced,auto tuning done in drive,direction checked and tested okay	06:00:00	10:15:00	