



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/09/2026

Incharge(s): Nagendra Midde

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	old day bin compressur	not working/RTD -AIR-TEMP.SENSOR FAULT	KEPT OFF AND STAND BY COMPRESSOR MADE ON	17:00:00	17:15:00	
2	OHP	CO 56 TO CO 57	CHUTE VIBRATOR NOT WORKING/POWER OFF	POWER MADE ON	17:10:00	17:30:00	POWER FEEDING TO HOIST PANEL
3	OHP	CO 26	TRIPPED ON OLR	RESET DONE	16:50:00 21:35:00	17:00:00 21:45:00	
4	OHP	CO 15A	TRIPPED ON OLR	RESET DONE	21:00:00	21:10:00	
5	CHP	RG 1	TRIPPED ON OVER CURRENT DUE TO JAMMING	RESET DONE	19:55:00	21:30:00	
6	CHP	CC 52	TRIPPED ON OLR	RESET DONE	19:30:00	19:40:00	
7	CHP	SCR 4 ON CC111	SIGNAL MISSING AND ALSO ALL MACHINES	MODEM -2 POWER RECYCLE DONE AT CCR	19:00:00	19:15:00	