



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 10/05/2026

Shift: B

Incharge(s): Lal Singh

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-85	OLR ACTED	RESET DONE	15:30:00	15:40:00	
2	OHP	CO-30 BRC	POWER PROBLEM ... ONE LUG CUT IN TRANSFORMER HT	LUGGING DONE AND TESTED	14:00:00	15:10:00	
3	OHP	TT-3	POWER MPCB NO BLOCK PROBLEM	BYPASSED	14:00:00	15:00:00	
4	OHP	CO-16	TRIPPED ON OLR	RESET DONE	15:00:00 19:30:00	15:10:00 19:40:00	
5	CHP	CC-39 SCR-7	BC NOT RUNNING SLEW 30 DEGREE ACTED	SLEW LEFT DONE	14:30:00 15:30:00	14:40:00 15:40:00	
6	CHP	CC-125	TRIPPED ON OLR	RESET DONE	17:40:00 21:15:00	17:45:00 21:25:00	
7	CHP	CC-36 R-1	SLEW NOT WORKING .. TYRE COUPLING LEFT NUT BOLT DAMAGED	INFORMED MECH	19:25:00	20:00:00	
8	CHP	CC-51	MPD TRIPPED	RESET DONE	16:20:00	17:00:00	
9	CHP	CC-131	TRIPPED ON OLR	RESET DONE	15:20:00 17:10:00	15:25:00 17:20:00	
10	CHP	CC-28	TRIPPED ON OLR	RESET DONE	14:30:00	14:40:00	
11	WT	OP-2	POWER SUPPLY TRIPPED AT LC-2A COL . NO 81	MADE ON	19:45:00	20:00:00	