



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/07/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CC-28 F/G	Reported not moving	Tripped.Made on	15:05:00	15:20:00	
2	OHP	CC-131	Reported tripped	OLR acted.Reset done	20:45:00	20:50:00	
3	OHP	CO-25	Reported tripped	OLR acted.Reset done	16:50:00	17:00:00	
4	OHP	CO-26	Reported tripped	OLR acted.Reset done	17:25:00 18:50:00	17:30:00 19:00:00	
5	OHP	WOBR on CO-25	LT not taking place	PCRD tension acted.Released and tested okay	16:00:00 20:20:00	16:10:00 20:35:00	
6	OHP	CO-5A	BRS not getting reset	Reset done and tested okay	19:35:00	19:50:00	
7	OHP	BRC on CO-32	Hydraulic pump not running	Healthy relay contact loose.Tightened and tested okay	20:30:00	20:55:00	
8	OHP	BRC on CO-32	Reported no power	ACB tripped due to power dip.Made on	17:35:00	17:55:00	NO delay
9	CHP	CC-31 SCR-1	B/C not running	30 degree slew limit acted	14:30:00	14:40:00	
10	CHP	CC-37 SCR-3	B/C not running	OLR acted.Reset done	18:30:00	18:40:00	
11	CHP	Cc-203	CJD acted	Material jamming found.	14:30:00	14:50:00	Informed to operation



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/07/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	CHP	CC-115	ZSS acted	Checked and found motor side coupling hub damaged and gearbox damaged.	15:05:00	15:15:00	Motor coupling hub changed and gearbox changed by mechanical and clearance given at 8.50pm
13	WT	OP-10	Reported not healthy	Tripped in LC-10B.Made on	14:10:00	14:20:00	
14	WT	OT-5	Outhaul sensor bypassed	kept in line	14:52:00	15:00:00	