वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 11/10/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	OLR acted	Reset done	22:35:00	22:45:00	
2	OHP	CO-26	OLR acted	Reset done	04:30:00	04:35:00	
3	OHP	BRC ON CO-8A	LT unhealthy. Drive tripped	Reset done	02:40:00	02:55:00	
4	OHP	CO-11	Stopping on ZSS. Found cage got struck up.	cage replaced	22:30:00	23:10:00	
5	OHP	CF-1	Unhealthy. Found chute sensor misalignment	properly adjusted and made OK	00:30:00	00:50:00	
6	CHP	SCR-2 ON CC-33	GVM side signal not coming. Checked and found cable got cut near to the sensor.	Bypassed and given clearance.. No delay	22:45:00	23:10:00	sensor to be checked and changed
7	CHP	SCR-5 ON CC-32	LT unhealthy	Reset done	03:40:00	03:55:00	
8	CHP	SCR-2 ON CC-33	Signal missing. LT done and then also signal missing. Modem ping is found OK. Ethernet cable problem found.	Spare cable laid and made ok	03:30:00	04:30:00	
9	CHP	TIS ON CC-130	Motor tripped	Reset done	05:35:00	05:40:00	
10	CHP	CC-28	OLR acted	Reset done	22:20:00 22:50:00	22:25:00 23:00:00	
11	CHP	CC-14	OLR acted	Reset done	04:05:00 04:20:00	04:10:00 04:30:00	