



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 29/09/2026

Area: OHP

Equipment	Job
Misc.	Hvmcc-1 cable trench de watering is done. Spare motor for WBR-4 LT motor is found, coupling to be fixed. om-12,lc-8,lc-4 water levels checked and de watering is done.
co-9a ,56 gallery ; co-41a stair case area	lighting improved
vf-10 motor tripped	Observed heavy vibration and tripping due to high counter weight angle, reduced angle % from 90 to 60 and checked. Restored both motors in use.
brc-4 on co-8a	Oil cooler Fan Feeder Healthy was bypassed at IO rack. removed bypass and checked interlock
co-32	pullchord cable was damaged during JCB cleaning, rejoin done and restored in circuit.
tt-4 pcrd cable	tt-1 removed spare cable is used for full length in tt-4 and slip ring maintenance is done.
wobr-3 on co-25 pcrd motor	motor was having water accumulated inside, cleaned, dried and restored pcrd operations.