



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/05/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO-29	B/W not running	Motor meggered and made to run and smoke came out.Placement done for motor replacement and spare motor found	06:30:00	07:45:00	Motor replaced and clearance given at 12.10PM
2	OHP	CO-26	Reported tripped	OLR acted.Reset done(2 times)	06:30:00 08:10:00	06:35:00 08:15:00	
3	OHP	BRC on CO-8A	CT not taking place	MCCB in off condition.Made on	08:45:00	08:55:00	
4	OHP	WOBR on CO-26	Slewing not taking place	Drive tripped.Reset done	09:05:00	09:15:00	
5	CHP	Cc-54	Reported tripped	OLR acted due to decksheet jamming.Reset done(5 times)	11:15:00	12:00:00	
6	CHP	CC-201	Reported PC and Control off	Checked and found PC contact missing.Bypassed and given clearance	08:30:00	09:00:00	After checking found 3 Pc's were in operated condition.Reset done and bypass removed
7	CHP	CC-25,26,27	Reported not healthy	I/O rack 110V MCB tripped.Made on	06:30:00	06:50:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/05/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
8	CHP	CC-203	Reported tripped	OLR acted.Reset done	08:30:00	08:40:00	
9	CHP	Cc-218	Reported tripped	OLR acted.Reset done	10:15:00	10:25:00	
10	CHP	CC-33 SCR-2	Luffing not working	Oil temperature high.Bypassed at I/O rack.	12:55:00	13:10:00	Informed to mechanical
11	CHP	Cc-40	Reported tripped	Checked and found soft hard relay problem.replaced with new and tested okay	11:30:00	13:00:00	