



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 03/05/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CR 2 and 3	lub pump not healthy	reset	11:15:00	11:20:00	
2	OHP	RSCO 10 A(c)	mpcb tripped	reset	12:40:00	12:47:00	
3	OHP	wobr on co 26	b/c motor problem,	megger done found R-E value zero, motor with fluid coupling replaced with repair bay machine motor	06:00:00	11:05:00	
4	OHP	BRC on CO 28	b/c olr acted due to jamming	reset, phase sequence changed	08:30:00	08:45:00	
5	OHP	TBS on CO 23	luff and BC not working, olr acted	reset	07:25:00	07:45:00	
6	CHP	CC 31 scr1	slew not working, drive tripped	reset	08:55:00	09:10:00	
7	CHP	CC 51	mpd acted	reset	06:55:00	07:00:00	3 times
8	CHP	CC 54	OLR acted	reset	10:15:00	10:25:00	
9	CHP	CC 32	olr acted	reset	11:00:00	11:10:00	
10	WT	OP4	no movement, olr acted d2	reset	06:15:00	06:25:00	