



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/07/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	CHP	cc 104 scr 9	luff not working, 24V main solenoid valve fuse blown	fuse replaced	23:05:00	23:20:00	
2	CHP	cc 104 scr 9	b/w not working	fault reset	01:55:00	02:05:00	
3	CHP	CC 131	motor tripped, in phase fault, r phase i/c to mccb found lug cut	relugging and termination	01:22:00	01:55:00	
4	CHP	cc 131	mpr tripped	reset	04:05:00	04:10:00	