



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/07/2026

Incharge(s): M Kailash, Lal Singh

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR ON CO-29	Slewing not working. Found Drive tripped	reset done	22:20:00	22:30:00	
2	OHP	BRC ON CO-32	HYD. PUMP not starting. Found control MCB is in OFF condition	Made ON and tested OK	22:50:00	23:05:00	
3	OHP	BF-3A	Stopping in ZSS fault.	Found ZSS probe checknut loose. Tightened	01:00:00	01:15:00	
4	CHP	CC-52	MPR acted	Reset done	05:40:00	05:45:00	
5	CHP	SCR-7 ON CC-40	Boom conveyor tripped	Reset done and tested OK	01:07:00	01:21:00	
6	CHP	CC-107	Overload tripped	Reset done	03:00:00 04:25:00	03:05:00 04:30:00	