



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 17/06/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	wobr-2 on co-29	luff not taking place	olr acted, reset done	09:25:00	09:40:00	
2	OHP	brc-5 on co-32	no drives operating	acb tripped, made on and tested all drives	09:20:00	09:30:00	
3	OHP	TT-1 on co-7a	position indication is not coming	cable issue to be checked., bypassed at io rack and given for clearance for operation.	11:35:00	12:00:00	
4	OHP	tbs-6 on co-7a	no drives starting	acb tripped, made on	11:35:00	11:55:00	
5	OHP	tbs-6 on co-7a	LT not stopping with load	Brakes are not working , regulation along with mechanical is done.	12:10:00	12:30:00	
6	OHP	tbs-3 on co-21	reported stopped on cjd 3 times	kept bypass temporarily, checked along with instrumentation, and restored in circuit later on.	10:00:00	10:20:00	
7	OHP	TIS-2	TIS-2 mpcb tripped	reset done, kept bypass at io rack due to lump tripping as per operation requirement.	08:00:00	08:10:00	
8	CHP	S-3 on cc-111	BC not operating ,	slew is at 30 degrees, asked operator to operate slew OHP side, and started BC.	07:40:00	07:55:00	
9	CHP	s-3 on cc-111	yard conveyor stopped	due to comm. issue yard stopped, LT done and communication was restored.	08:20:00	08:35:00	
10	CHP	scr-5 on cc-38	TUL CJD acted,	material cleaned, and checked CJD operation and gave clearance for operation.	08:00:00	08:10:00	
11	CHP	cc-54	tripped on OLR 5 times	tripped due to deck sheets jamming, cleaned and reset done	09:00:00	10:15:00	
12	CHP	cc-51	feeding conveyor tripped 3 times	due to overload	11:00:00	13:15:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 17/06/2026

Incharge(s): P Venkat Kiran,P Venkat Kiran

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	CHP	cc-201,203, 204,205	not healthy	reset done.	07:30:00	07:40:00	
14	WT	ot-3 D2	TRIPPED ON 43 ENCODER FAULT	reset done	13:15:00	13:20:00	
15	WT	ot-3 d1	tripped on encoder 43 fault	reset done	13:00:00	13:10:00	
16	WT	co-4 carriage drive	tripped due to jamming	reset done	13:35:00	13:45:00	