



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 07/10/2026

Incharge(s): M Kailash

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	Pullcord unhealthy. Found CJB field fuse blown.	Bypassed in CJB	09:00:00	09:15:00	Informed to General shift
2	OHP	CO-25	Overload acted	Reset done	09:15:00	09:22:00	
3	OHP	CO-78	Pullcord unhealthy.	All pullcords acted and released. Then became healthy	09:10:00	09:35:00	
4	OHP	BRC ON CO-32	LT not moving. PCRD tension acted	Released and made OK	12:35:00	12:45:00	
5	OHP	BRC on CO-8A	LT not working. Found M-1,3 tripped in drive 2 panel	Reset done	10:05:00	10:20:00	
6	CHP	CC-125	Tripped on overload	Reset done	09:00:00	09:05:00	
7	CHP	CC-22	Tripped on overload due to jamming	Reset done	11:20:00	11:30:00	
8	IOSA	WOBR ON OC-17A	LT drive tripping. Found track jamming and motors M-6,7 problem.	Motors isolated	06:00:00	07:15:00	Track jamming and no electrical problem