वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 18/10/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 25	OLR acted	reset	08:40:00	08:50:00	2times
2	OHP	CO 29	olr acted	reset	11:15:00	11:25:00	
3	OHP	CR1 A	MPR tripped due to OL	reset and informed operation	11:00:00	11:15:00	
4	OHP	BRC on CO 32	b/c not running,due to alignment of probe disturbed	probe alignment adjusted	10:30:00	10:45:00	
5	OHP	CC 32 scr5	LT not working,PCRD OT acted	released	08:55:00	09:05:00	
6	CHP	CC 58	tripped	reset	09:05:00	09:20:00	
7	CHP	CC 201,203	OLr acted	reset	07:10:00	07:20:00	
8	CHP	CC 32 scr2	LT not working OT acted	released	08:20:00	08:30:00	
9	CHP	CC 40 scr7	b/c signal missing	LT done than ok	10:50:00	11:00:00	
10	CHP	CC 111 scr4	slew not working,	wrong complaint	13:00:00	13:10:00	
11	CHP	CC 26	TT flap gate mpcb	reset	09:10:00	09:20:00	
12	WT	CP 3	no movement,fwd limit acted	released	09:30:00	09:35:00	