



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/09/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 36	not healthy,PC acted,PC switch was damaged	PC bypassed @8.15	08:10:00	08:15:00	switch replaced and kept in ckt10.15
2	OHP	wobr on co 29	slew not working,drive tripped	reset	06:20:00	06:30:00	
3	OHP	wobr on co 6A	slew not stopping,Push button problem	PB adjusted	08:30:00	08:45:00	
4	OHP	BRC on CO 32	BC not running,PB stucked	PB releasd	08:50:00	09:00:00	
5	OHP	co 26	olr acted	reset	11:30:00	11:35:00	
6	OHP	BRC on CO28	b/w 1 and 2 not running	power recycled done	11:00:00	11:15:00	
7	OHP	TBS on CO22	LT not working,due to PCRD OT acted,cable fallen,chain broken	informed operation and mechanical	12:20:00	12:30:00	
8	OHP	OP2	no movement,D4 olr acted	olr reset	06:00:00	06:20:00	D6 kept in ckt,cascade contactor kept in ckt
9	OHP	RSCO 10 A(B)	olr acted	reset	09:50:00	10:00:00	
10	OHP	OT 4	d1 tripped in PGF1 fault	reset	09:05:00	09:10:00	
11	CHP	CC 28	flap gate tripped	reset	11:40:00	11:50:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/09/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	CHP	CC 52	mpd acted	reset	06:00:00	06:10:00	2 times
13	CHP	CC 33 scr2	b/w not working,drive tripped due to OL	reset	07:45:00	07:55:00	
14	CHP	CC 40 SCR7	b/c not running,communication problem	LT done than ok	09:12:00	09:25:00	
15	WT	CO 3(B)	mpcb tripped	made on	10:30:00	10:35:00	