



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/09/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-11A	Reported tripped	OLR acted.Reset done	08:20:00	08:25:00	
2	OHP	ALL stacker s,reclaimers ,wobr's	Power restoration	Breakers made on and made healthy	07:00:00	08:20:00	
3	OHP	TBS on CO-7A	Right boom ZSS acting	Loose contact found at module.Tightened and tested okay	08:00:00	08:15:00	
4	OHP	BRC on CO-28	NO operations taking place	ACB tripped.Made on	09:00:00	09:20:00	
5	OHP	TBS on CO-22	CJD not healthy	Checked and found fuse blown at TB.Replaced and tested okay	09:30:00	09:50:00	
6	OHP	WOBR on CO-25	PCRD cable lying on ground	Motor to PCRD drum chain broken.	08:00:00	08:20:00	Informed to mechanical. After rectifying cable rewinding done
7	OHP	ALL LC's,H VMCC's and OM's	Power restoration	Power restoration done after clearance from LBSS and tested okay	07:00:00	08:20:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 14/09/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
8	CHP	ALL machines and LC's, OM's and HVMCC's	Power restoration for all machines and OM's, LC's and HVMCC's	After clearance from LBSS, all machines, LC's, OM's, HVMCC's power restoration done and checked and tested okay	07:00:00	08:00:00	
9	CHP	SCR-1 on CC-31	Slewing not taking place	30 degree limits not healthy due to jamming	12:30:00	12:45:00	Informed to operation
10	CHP	SCR-7 on CC-40	B/C not running	OLR acted. Reset done	12:30:00	12:40:00	
11	CHP	SCR-4 on CC-111	B/C stopping frequently	No problem found	12:45:00	12:55:00	
12	CHP	R-1 on CC-39	B/c not running	Fault reset done and tested okay	10:20:00	10:30:00	
13	CHP	CC-29 TT on CC-111	Position bit missing	Bypassed and after rectification kept in line	10:10:00	12:10:00	
14	WT	ALL WT's and Pushers	Power restoration	After clearance all tiplers and pushers made healthy and checked and tested okay	07:00:00	07:50:00	
15	IOSA	PLC communication	After power restoration PLC communication faulty	Power recycled at ALL OM's and communication restored	07:00:00	08:00:00	
16	IOSA	PLC communication problem	Stacking conveyors not healthy	Power recycled at OM-4, LC-1, OM-1 and LC-9 and communication restored and tested okay	11:00:00	11:35:00	