



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/09/2026

Incharge(s): Saurabh Kumar Yadav

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	wobr on co 29	LT not working,OT acted	OT released	23:10:00	23:25:00	
2	OHP	BRC on co 30	CT not working,drive tripped	reset	03:15:00	03:22:00	
3	OHP	CO 10 A	olr acted	reset	01:10:00	01:20:00	
4	CHP	cc 33 scr2	b/c not running,signal missing	LT done than ok	04:40:00	05:10:00	
5	CHP	CC 131	motor tripped due to ol	reset	05:40:00	05:45:00	
6	WT	OT 2	D1 tripped in pgf1 fault 20 times	drive reset,encoder replaced D1 side,mechanical tightened coupling main shaft for tippler connector nut bolt	01:25:00	03:00:00	