



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/10/2026

Incharge(s): M Kailash

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	OLR acted	reset done	07:00:00 11:15:00	07:10:00 11:25:00	
2	OHP	CO-111	OLR acted due to jamming	Reset done	08:40:00	08:50:00	
3	OHP	WOBR ON CO-29	LT not taking place. PCRD tension acted	Released and made OK	10:35:00	10:50:00	
4	OHP	TBS on CO-7A	Luffing not working due to drive trip	Reset done	11:10:00	11:20:00	
5	OHP	CO-11A	Pullcord not healthy. Checked and found cable damaged due to mechanical work	Bypassed and given clearance	10:30:00	11:00:00	cable problem to be rectified
6	OHP	CO-12A	BRS is not getting reset after acting. Reset pushbutton not working properly	Kept in bypass and Made reset. Kept under observation	12:40:00	13:10:00	Module/ Reset pushbutton to be changed