



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 25/06/2026

Area: OHP

Equipment	Job
co-28,27a,30a	safety devices ppm is done.
co-28,27a,30a	safety devices ppm is done.
co-67 to 70 ; 36a to 36b chute vibrators	ppm is done., co-66 to 69 chute vibrator bearing got stuck, replaced with spare one, overhauling is to be done.
co-67 to 70 ; 36a to 36b chute vibrators	ppm is done., co-66 to 69 chute vibrator bearing got stuck, replaced with spare one, overhauling is to be done.
co-44 h/e, 13a h.e hoists, Bombay Crane	Hoists ppm is done
co-44 h/e, 13a h.e hoists, Bombay Crane	Hoists ppm is done
co-50 T/E ; co-14a gallery ;	lighting is improved ;
co-50 T/E ; co-14a gallery ;	lighting is improved ;
Old Thruster Brakes removed from TBS-6	overhauling job started at hvmcc-1
Old Thruster Brakes removed from TBS-6	overhauling job started at hvmcc-1
tbs-3 on co-21	RBC pile focus lamp 350W installation work is done.
tbs-3 on co-21	RBC pile focus lamp 350W installation work is done.
1-14lc4, om-22	RIO bypass inspection is done and recorded.
1-14lc4, om-22	RIO bypass inspection is done and recorded.
wobr-1 on co-26 Luff Down limits	checked and kept in circuit.
wobr-1 on co-26 Luff Down limits	checked and kept in circuit.
tbs-1 on co-23	shifted to co-22



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 25/06/2026

Area: OHP

Equipment	Job
tbs-1 on co-23	shifted to co-22
co-15 Contactor incoming Y phase RI defect	Replaced lug .
co-15 Contactor incoming Y phase RI defect	Replaced lug .
co-2a,rsc0-10a, ; tbs-7 on co-19, co-19	motor and panel side ppm is done.
co-2a,rsc0-10a, ; tbs-7 on co-19, co-19	motor and panel side ppm is done.
co-5a power plug panel	F26 DC control MCB failed, replaced and restored supply to TBS on co-5a
co-5a power plug panel	F26 DC control MCB failed, replaced and restored supply to TBS on co-5a