



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 05/09/2026

Area: OHP

Equipment	Job
brc-4 on co-8a	HT slip ring maintenance was done.
vf-15a chute vibrator	chute vibrator motor was found hanging, mother plate damaged, informed mechanical.
TBS on co-5A	Boom Run FB and CJD bits at the TBS RMU were interchanged, and the corresponding changes were also incorporated in the Siemens PLC program.
BRC-3 on co-33m	shifted from co-33m to co-34. M1 motor sound observed, decoupled it and removed coupling was fixed for M2. m1 motor to be replaced. PCRD gear box has mechanical Issue , cable loop was provided and drum was tied.