



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/07/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO-32	Reported hydraulic pump not running	Oil level low.	14:50:00	15:05:00	Informed to mechanical
2	OHP	WOBR on CO-29	Luffing not working	OLR acted.Reset done	18:45:00	18:55:00	
3	OHP	CO-70	Reported not healthy	DMPR not healthy.Bypassed keeping BCH OLR in line	19:30:00	19:40:00	
4	CHP	VF-3	Reported tripped	Drive tripped on ovn fault.Reset done	18:30:00	18:45:00	
5	CHP	Cc-51A	Reported tripped	OLR acted.Reset done	16:00:00	16:05:00	
6	CHP	Cc-54	Reported tripped	OLR acted.Reset done(6 times)	17:40:00	20:05:00	
7	CHP	CC-201	Reported tripped	OLR acted.Reset done	15:15:00	15:20:00	
8	CHP	CC-28	Reported tripped	OLR acted.Reset done	16:20:00 20:45:00	16:30:00 20:50:00	
9	CHP	Cc-28	F/G tripped	OLR acted.Reset done	20:50:00	21:00:00	
10	CHP	CC-37 SCR-3	LT not working	PCRD tension acted.Released and tested okay(2 times)	19:05:00	20:15:00	
11	CHP	CC-37 SCR-3	B/C not running	Probe check nut loose.Tightened and tested okay	15:50:00	15:55:00	
12	CHP	CC-104 R-1	B/C not running	Probe problem.Replaced and tested okay	14:50:00	15:15:00	
13	WT	OT-1	Stopping frequently	Control tightening done and tested okay	18:50:00	19:15:00	
14	WT	OP-6	Reported not moving	Breaker tripped at LC.Made on.	20:30:00	21:00:00	