



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/07/2026

Incharge(s): Saurabh Kumar Yadav

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC 8A	all drive not working,acb tripped	made it on	06:50:00	07:10:00	
2	OHP	CO 78	ZSS acted,probe cable came disconnected due to mech job	re connected	10:45:00	11:00:00	
3	CHP	CC 130 TIS	olr acted due to heavy material	reset	09:00:00	09:10:00	
4	CHP	CC 28 TT	on 33 position not showing,sensor having dust	sensor cleaned	09:40:00	09:50:00	
5	CHP	CC 28 TT	chute sensor cable damaged	cable properly rejoined	10:05:00	10:15:00	
6	CHP	CC 29	zss acted,coal stucked in cage	cage made free	10:20:00	10:30:00	
7	CHP	CC 201	olr acted,PC acted	reset and PC released	10:50:00	11:00:00	
8	CHP	CC 29	olr acted	reset	13:20:00	13:25:00	
9	WT	EOT	CT not working,contactor problem	contactor properly adjusted	11:00:00	11:20:00	