वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 26/10/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | tbs on co 7a | LT not working,olr acted | reset | 02:05:00 | 02:20:00 | |
| 2 | OHP | co 25 | olr acted | reset | 05:20:00 | 05:25:00 | |
| 3 | OHP | brc on co 32 | LT not working,olr acted | reset | 05:00:00 | 05:20:00 | |
| 4 | OHP | CO 70 | mpr acted,mpr problem not getting reset | bypassed | 05:45:00 | 05:55:00 | to be changed |
| 5 | CHP | CC 131 | motor tripped,olr acted | reset | 03:30:00 | 03:35:00 | 2 times |
| 6 | CHP | CC 54 | olr acted | rset | 02:00:00 | 03:00:00 | 3 times |
| 7 | CHP | CC 112 | S3,bc not running,tripped in CURT SP fault | reset | 22:40:00 | 22:55:00 | |
| 8 | WT | OP9 | communication problem | ethernet cable unplugged ,cleaned and re plugged in modem of OT5 bridge and power recycle | 02:30:00 | 03:15:00 | way to tippler blocked due to wagon grouping |