वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 05/11/2026

Shift: A

Incharge(s): Amit Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | CO-25 | Reported tripped | OLR acted.Reset done | 06:00:00 | 06:05:00 | |
| 2 | OHP | CO-26 | Reported tripped | OLR Acted(4 times) | 07:50:00 | 13:50:00 | |
| 3 | OHP | TBS on CO-19 | Reported no operations taking place | B/C not running due to chute jamming and gearbox oil leakage | 06:25:00 | 06:40:00 | Informed to operation |
| 4 | OHP | WOBR on CO-25 | Slewing not taking place | Wrong complaint | 13:15:00 | 13:25:00 | |
| 5 | OHP | Cc-131 | Reported tripped | OLR acted.Reset done | 11:10:00 | 11:15:00 | |
| 6 | OHP | Vs-2A | Reported tripped | OLR acted.Reset done(2times) | 10:05:00 | 10:32:00 | |
| 7 | CHP | Cc-54 | Reported tripped | OLR acted.Reset done | 08:30:00 | 08:35:00 | |
| 8 | CHP | LC-19 | I/C-2 tripped | Reset done and tested okay | 11:20:00 | 11:25:00 | |
| 9 | CHP | CC-112 S-3 | Slewing not taking place | Jamming found | 08:40:00 | 08:50:00 | Informed to opration |