



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/07/2026

Shift: C

Incharge(s): Nagendra Midde, G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-24	HT power problem. Two HT fuses blown. Checked and found fixed coupler Head problem	After DNW work, charged and given clearance	22:00:00	23:20:00	
2	OHP	BRC-1 ON CO-28	Boom conveyor not stating. Overload acted	Reset done	03:15:00	03:25:00	
3	OHP	CO-1A	Pullcord not acted but showing pullcord acted	bypassed and checked pullocrds. Found pullcord acted. Released and kept in circuit	00:20:00	00:40:00	Not reset done by operation
4	CHP	CC-125	Overload trip	Reset done	00:10:00	00:15:00	
5	CHP	CC-107	Overload trip	Reset done	03:35:00	03:40:00	
6	CHP	CC-54	Tripped on Overload	Reset done	02:20:00	02:25:00	
7	CHP	CC-107	Overload acted	Reset done	05:35:00	05:40:00	