



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 03/08/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 26	OLR acted	reset	01:50:00 23:57:00	02:00:00 00:02:00	
2	OHP	wobr on co 25	LT not working,OT acted	OT released	02:20:00	02:35:00	pcrd pendulum switch to be checked
3	OHP	CO 34	OLR acted	reset	03:45:00	03:55:00	
4	OHP	VS 3A	OLR acted	reset	23:05:00	23:15:00	
5	CHP	CC 131	mpd acted	reset	05:05:00	05:10:00	
6	CHP	CC 54	motor tripped on OLR	reset	02:15:00	02:20:00	5 times
7	CHP	cc 28	flap gate tripped	reset	23:20:00	23:30:00	
8	CHP	CC 201	olr acted	reset	23:40:00	23:50:00	
9	CHP	CC 104 scr 9	BRS acted due to moisture and rain water	sensor cleaned	22:30:00	23:10:00	
10	CHP	CC 31 scr 1	motor tripped	reset	04:20:00	04:30:00	
11	CHP	CC 105 scr 10	signal missing,	LT done than ok	04:10:00	04:25:00	
12	CHP	CC 32	motor tripped	reset	05:15:00	05:25:00	
13	CHP	CC 125	olr acted	reset	04:20:00	04:25:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 03/08/2026

Incharge(s): Saurabh Kumar Yadav

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	WT	CP 4	not running complaint, from last five days no rack was there.....pusher @col no 38 B PHASE c and Uclamp problem pad fallen	called traffic, engine is to be entered in CP3 line	04:45:00	05:00:00	middle c and U clamp to be changed after getting power block
15	IOSA	oc17 A	ZSS acted,because probe getting covered with water	module and probe cleaned	23:50:00	00:15:00	