वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 03/11/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	wobr on co 26	luff not work ,mpcb tripped	mpcb made on	15:05:00	15:15:00	
2	OHP	tbs on co 20	LT not working,M1 tripped	made on	15:15:00 17:35:00	15:30:00 17:45:00	
3	OHP	co 25	olr acted	reset	17:15:00	17:25:00	times
4	OHP	co 26	olr acted	reset	18:10:00	18:20:00	
5	OHP	brc on co 31	zss yard interlock not coming,probe alignment disturbed	probe adjusted	18:15:00	18:35:00	
6	OHP	bf 3A	zss cable got cut	re jointed	15:30:00	15:40:00	
7	OHP	VF 10A	olr acted	reset	16:30:00	16:40:00	
8	CHP	CC 131	motor tripped due to olr	reset	21:25:00	21:30:00	
9	CHP	CC 40 SCR7	b/c not running,mpd tripped	reset	16:30:00	16:40:00	3 times
10	CHP	CC 37 SCR3	LT not working,M4 tripped	reset it	15:50:00	16:05:00	2 times
11	IOSA	OC 25A	HEALTHY STOP,	DID ack than healthy	18:30:00	18:40:00	
12	IOSA	new wobr	IM module of rack 2 unhealthy,Di card loose connection	tightened	18:45:00	19:45:00	no delay,machine not running,it will run tomorrow