



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 22/05/2026

Shift: B

Incharge(s): Lal Singh

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RSCO-6A	TRIPPED IN OLR	RESET DONE	17:00:00	17:15:00	
2	OHP	BRC ON CO-30	LT NOT MOVING	EMERGENCY STOP .. RELEASED AND TESTED	17:20:00	17:35:00	
3	OHP	TBS ON CO-21	BC ZSS PROB PROBLEM	REPLACED AND TESTED	20:15:00	20:30:00	
4	OHP	CO-6A WBR	LT NOT WORKING	DRIVE TRIPPING IN GROUND FAULT ... M-5 MOTOR PROBLEM ... REMOVED AND TESTED	21:30:00	22:00:00	
5	CHP	CC-51	MPD TRIPPED	RESET DONE	15:50:00	15:55:00	
6	CHP	CC-131	TRIPPED ON OL	RESET DONE	15:55:00	16:00:00	
7	CHP	CT-2	NOT MOVING	BREAK NOT HEALTHY	21:52:00	22:00:00	CHECKING GOING ON
8	WT	CC-201	TRIPPED ON OL	RESET DONE	17:00:00	17:10:00	
9	WT	CO-2	CHUTE SENSOR ACTED ... LOOSE CONNECTION IN MODULE	FIXED	16:30:00	16:50:00	
10	WT	CT-2	BREAK RECTIFIER FAILED ..	REPLACED FROM SHIFT ROOM SPARE WHICH ALSO FAILED AFTER ONE ROUND THEN SPARE REMOVED FROM LC-1 AND FIXED IN CT -2 AND TESTED	18:40:00	20:35:00	
11	WT	CP-4	BREAKER TRIPPED	MADE ON	20:40:00	20:50:00	
12	WT	OP-1	BREAKER TRIPPED	MADE ON	21:00:00	21:10:00	
13	WT	OP-6	NOT MOVING .. INCOMER TRIPPED	MADE ON	21:20:00	21:40:00	