



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 05/06/2026

Incharge(s): Amit Roy

Shift: C

| Sl No | Area | Equipment    | Problem                      | Action                                                                                                                                                             | From                             | To                               | Remarks                |
|-------|------|--------------|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|----------------------------------|------------------------|
| 1     | OHP  | CC-125       | Reported tripped             | OLR acted.Reset done                                                                                                                                               | 00:20:00<br>03:25:00<br>05:20:00 | 00:30:00<br>03:30:00<br>05:25:00 |                        |
| 2     | OHP  | TBS on CO-21 | LT not taking place          | PCRD tension acted.Released                                                                                                                                        | 03:35:00                         | 03:50:00                         |                        |
| 3     | OHP  | CO-11A       | BRS acted                    | Due to belt piece                                                                                                                                                  | 02:30:00                         | 02:40:00                         | Informed to operation  |
| 4     | CHP  | Cc-45        | Reported fail to start       | Checked and found IM module both faulty.Profibus connectors removed and again put back.Redundancy line module bus fault found and kept out of line and tested okay | 23:00:00                         | 23:30:00                         |                        |
| 5     | CHP  | Cc-104 SCR-6 | LT and slew not taking place | Slew olr acted.Reset done LT PCRD tension acted due to tack jamming                                                                                                | 23:55:00                         | 00:00:00                         | Inforemed to operation |
| 6     | CHP  | CC-112 SCR-8 | BC not running               | Cage stuck with coal.Made free                                                                                                                                     | 02:40:00                         | 03:05:00                         |                        |
| 7     | CHP  | CC-38 SCR-5  | LT not taking place          | M-5 acted due to track jamming.Reset done                                                                                                                          | 03:15:00                         | 03:25:00                         |                        |
| 8     | CHP  | CC-29        | ZSS acted                    | Cage stuck.Made free                                                                                                                                               | 03:55:00                         | 04:00:00                         |                        |
| 9     | CHP  | Cc-51        | MPD tripped                  | OLR acted.Reset done                                                                                                                                               | 04:00:00<br>23:25:00             | 04:05:00<br>23:35:00             |                        |
| 10    | CHP  | Cc-115       | BRS not working              | Sensor cleaning done and tested okay                                                                                                                               | 23:40:00                         | 00:00:00                         |                        |
| 11    | WT   | OT-4         | Reported tripped             | D-2 tripped on PGEF-4 fault.Reset done                                                                                                                             | 02:10:00                         | 02:15:00                         |                        |