



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 11/07/2026

Incharge(s): Lal Singh

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO-21	C/S acting	Probe cleaning done and tested okay	23:15:00	23:30:00	
2	OHP	WOBR on CO-25	LT not working	M-4 tripped due to belt piece stuck under the wheel.	03:30:00	03:45:00	
3	CHP	CC 215	Reported tripped	MPD tripped.Reset done	23:45:00	23:55:00	
4	CHP	CC 213 SCR-9	Signal frequently missing	Modem replaced from SCR-7 and tested okay	02:00:00	02:30:00	
5	CHP	Cc-107	Reported tripped	MPD tripped.Reset done	01:35:00	01:40:00	
6	CHP	CC-37 SCR-3	LT not working	Drive tripped.Reset done	01:40:00	01:50:00	
7	CHP	CC-201	Reported tripped	OLR acted.Reset done	01:30:00	01:35:00	
8	CHP	CC-212	Reported tripped	Drive tripped.Reset done	02:35:00	02:45:00	
9	CHP	CC-58	Reported tripped	SPP tripped.Reset done	05:50:00	06:00:00	
10	WT	OT-3	Reported not healthy	Drive-1 tripped on encoder-43 fault.Reset done	02:10:00 02:50:00	02:15:00 02:55:00	