वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 31/10/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | co 25 | olr acted | reset | 14:22:00 | 14:35:00 | 3 times |
| 2 | OHP | co 26 | olr acted | reset | 20:10:00 | 20:30:00 | |
| 3 | OHP | TBS on CO 7A | LT not working,control is in off | made it on | 16:30:00 | 16:45:00 | |
| 4 | OHP | TBS on CO 7A | left luff not working | wrong complaint | 18:00:00 | 18:15:00 | |
| 5 | OHP | WOBR on CO 29 | LT not working,drive tripped | reset | 18:55:00 | 19:10:00 | |
| 6 | OHP | TBS on Co 7A | LT not working,M4 mpcb tripped | made it on | 20:05:00 | 20:15:00 | |
| 7 | OHP | TT3 on CO 22 | position bit missing,sensor wire loose connection | tightened | 16:15:00 | 16:30:00 | |
| 8 | OHP | VS 2 A | olr acted | reset | 17:50:00 | 18:10:00 | |
| 9 | OHP | co 36 | zss acted,probe wire got cut,and high return from ZSS not connected in cjb | probe replaced,return wire connected in cjb | 16:45:00 | 17:30:00 | |
| 10 | CHP | CC 52 | PC acted | PC reset | 14:35:00 | 14:45:00 | |
| 11 | CHP | CC 53 | pc acted | released | 14:40:00 | 14:50:00 | |
| 12 | CHP | CC 215 | zss problem | ZSS replaced | 14:00:00 | 14:45:00 | |
| 13 | CHP | CC 35 STK2 | LT not working,M2 tripped,pcrd guide problem | reset,informed mechanical | 14:35:00 | 14:45:00 | |
| 14 | CHP | CC 213 SCR8 | bc not running,signal missing | LT FWD done than ok | 18:45:00 | 19:00:00 | |

वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 31/10/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 15 | CHP | CC 40 SCR7 | c/s acted due to jamming | informed operation | 19:20:00 | 19:30:00 | |
| 16 | CHP | CC 201 and 203 | olr acted | reset | 14:30:00 | 14:40:00 | |
| 17 | CHP | CC 201 flap gate | mpcb tripped due to gate stucked | reset | 15:00:00 | 15:10:00 | |
| 18 | CHP | CC 203 | olr acted | reset | 20:30:00 | 20:40:00 | |
| 19 | WT | CP4 | FLS acted | reset | 19:20:00 | 19:25:00 | |