# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 30/10/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | RSCO 6A(c) | olr acted | reset | 15:45:00 | 16:00:00 | |
| 2 | OHP | RSCo9A(c) | mpcb tripped | reset | 17:00:00 | 17:10:00 | |
| 3 | OHP | CC 105 scr 10 | LT not working,OT acted | released | 14:50:00 | 15:00:00 | |
| 4 | OHP | co 26 | olr acted | reset | 18:00:00 | 18:10:00 | 3 times |
| 5 | OHP | wobr on co 29 | LT not working,drive tripped in OL | reset,checked and found D1 gear box oil leakage | 18:00:00 | 18:15:00 | 3 times tripped in ol,kept in DOL mode |
| 6 | OHP | TBSc on Co20 | R BC luffing not working,olr acted | reset | 17:25:00 | 17:35:00 | |
| 7 | OHP | CO 25 | olr acted | reset | 18:25:00 | 18:35:00 | 2 times |
| 8 | CHP | CC 14 | zss acted,coal stucked in cage | cage cleaned | 18:00:00 | 18:10:00 | |
| 9 | CHP | CC 51A | zss acted 2 times,stone stucked | removed | 19:40:00 | 19:50:00 | |
| 10 | CHP | CC 37 SCR3 | LUFF not working,oil level low | informed mechanical | 15:30:00 | 15:40:00 | |
| 11 | CHP | CC 105 scr10 | slew not working,coal jamming in slew area | informed operation | 18:05:00 | 18:15:00 | |