



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/06/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	Reported tripped	OLR acted.Reset done	00:15:00 22:10:00	00:20:00 22:15:00	
2	OHP	CO-25	Reported tripped	OLR acted.Reset done	23:20:00	23:30:00	
3	OHP	WOBR on CO-6A	Reported LT not taking place	M1 OLR acted.Reset done	02:10:00	02:25:00	
4	OHP	TBS on CO-7A	Reported LBC not running	MCCB tripped due to chute jamming.Made on	04:40:00	04:55:00	
5	CHP	CC-51	MPD tripped	Reset done	00:45:00	00:52:00	
6	CHP	Cc-54	ZSS acting	Checked and found ZSS to be working fine.Belt not running due to chute liner stuck at chute	03:20:00	03:40:00	Informed operation and mechanical
7	CHP	Cc-54	Reported tripped	OLR acted.Reset done	02:55:00 03:20:00	03:00:00 03:25:00	
8	CHP	CC-31	Reported tripped	OLR acted.Reset done	02:25:00	02:35:00	
9	CHP	CC-38 SCR-56	Slewing not taking place	30 degree limit acted.Released and tested okay	05:00:00	05:15:00	
10	CHP	CC-29	ZSS acting	Cage stuck with coal.Made free	22:50:00	23:00:00	
11	CHP	Cc-28	Reported tripped	OLR acted.Reset done	02:50:00	02:55:00	