



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 22/08/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 25	olr acted	reset	23:00:00	23:10:00	3 times
2	OHP	BRC on co 28	BC not running,olr acted	reset	02:45:00	02:55:00	
3	OHP	co 26	olr acted	reset	02:25:00	02:35:00	
4	OHP	CO 15	healthy stop,due to position bit missing on Co 22,plate not fixed properly	informed operation	01:45:00	02:00:00	
5	CHP	CC 54	olr acted	reset	01:45:00	01:50:00	
6	CHP	CC 38 SCR6	slew not working,coal jamming	informed operation	00:30:00	00:35:00	
7	CHP	CC 33 SCR2	LT not working,PCRD drum sensor acted	released	01:20:00	01:30:00	
8	WT	OT 5	D1 tripped in encoder fault spf	encoder replaced	22:00:00	22:30:00	no delay ,no rake