



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 20/08/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO-21	B/C not running	Motor running,pulley rotating belt not moving due to jamming.Luffing down done and made to run and cleared material	10:40:00	11:00:00	
2	OHP	CO-29	Reported tripped	OLR acted.Reset done	07:30:00 10:30:00	07:40:00 10:40:00	
3	OHP	TBS on CO-21	LT not taking place	PCRD tension acted.Released	10:30:00	10:45:00	
4	OHP	BRC on CO-8A	Lt not taking place	Operator cabin reset done	10:50:00	11:00:00	
5	CHP	CC-111,112	Reported no power	Checked and found I/C-1 tripped in LC-2.Made on	06:35:00	06:50:00	
6	CHP	CC-37 SCR-3	B/C not running	OLR acted.Reset done	08:45:00	08:55:00	
7	CHP	CC-26A,CC -40,38 BRS	Reported not healthy	CM-15 PLC rack earth fault. All DI cards removed and again put back and control made on and made healthy.	12:16:00	12:50:00	One DI card arm to be replaced
8	CHP	Cc-131	Reported tripped	OLR acted.Reset done	10:25:00 12:35:00	10:30:00 12:40:00	
9	CHP	CM-36	Reported tripped	Breaker charged and tested okay	06:40:00	06:55:00	
10	WT	OP-1	Reported not moving	Emergency acted.Released and tested okay	08:20:00	08:30:00	