



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 22/05/2026

Shift: C

Incharge(s): Nagendra Midde

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CC 130	MECH BRS ACTING DUE TO BELT PIECE	CUT IT THEN OK	02:45:00	03:00:00	
2	OHP	TBS ON CO 21 LBC	ZSS PROBE DAMAGED	REPLACED	05:35:00	05:50:00	
3	CHP	SCR 2 ON CC 33 SIGNAL	ETHERNET CONNECTIONS TIGHTENED NEAR MODEM	THEN OK	22:50:00	23:30:00	
4	CHP	SCR 5 ON CC 38 SIGNAL MISSING	MODEM FROM S3 ON CC 111 REPLACED	THEN OK	23:00:00	00:30:00	
5	WT	OT 3	D2 TRIPPING ON 7 SATURATION FAULT	RESET	22:30:00	05:30:00	7 TIMES
6	WT	CT 2	M2 BREAK LUG AND BRIDGE RECTIFIER PROBLEM REPLACED,	REPLACED	23:00:00	01:00:00	
7	WT	CP 4	BREAKER TRIPPED	MADE IT ON	22:45:00	22:55:00	
8	WT	OP1	BREAKER TRIPPED	MADE IT ON	00:30:00 01:00:00	00:40:00 01:10:00	
9	WT	OP1	CABLE PROBLEM AT COL 35	C TYPE POWER ISOLATED AT 48	03:00:00	03:30:00	