



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 26/05/2026

Incharge(s): G Eswara Rao

Shift: A

| Sl No | Area | Equipment     | Problem                                         | Action                                                            | From     | To       | Remarks                                               |
|-------|------|---------------|-------------------------------------------------|-------------------------------------------------------------------|----------|----------|-------------------------------------------------------|
| 1     | OHP  | TBS ON CO 7A  | LT NOT TAKING PLACE                             | CONTROL MADE ON AT CABIN                                          | 11:10:00 | 11:30:00 | LT NOT STOPPING ON LOAD /INFORM TO MECH .AND ADJUSTED |
| 2     | OHP  | WOBR ON CO 29 | BC NOT RUNNING/CONTROL OFF DUE TO LOWER CUTTING | LUFFING UP DOWN THEN OK                                           | 06:35:00 | 06:45:00 |                                                       |
| 3     | OHP  | WOBR ON CO 29 | LT NOT TAKING PLACE/CABLE TENSION ACTED         | MECH .PROBLEM EXISTING NO GEAR BOX/ RELEASED NO CABLE ON THE DRUM | 11:55:00 | 12:00:00 |                                                       |
| 4     | CHP  | SCR 1 ON CC31 | BC SIGNAL MISSING/2 TIMES                       | LT DONE THEN OK                                                   | 07:00:00 | 07:20:00 |                                                       |
| 5     | CHP  | CC 58         | TRIPPED ON OLR                                  | RESET DONE                                                        | 07:40:00 | 07:50:00 |                                                       |
| 6     | CHP  | CC II4        | REPORTED FAIL TO START                          | DIDNT FOUND ANY PROBLEM NEUTRAL MISSING AT MODULE                 | 12:50:00 | 13:10:00 | SLIDING CONTACTS TO BE CHECKED                        |
| 7     | CHP  | SCR 1 ON CC31 | LT NOT TAKING PLACE                             | PCRD TENSION ACTED/RELEASED                                       | 06:45:00 | 07:00:00 |                                                       |
| 8     | CHP  | SCR 2 ON CC33 | PCRD DRUM FAST SIGNAL ACTED                     | RESET DONE                                                        | 07:15:00 | 07:35:00 |                                                       |
| 9     | CHP  | CC 125        | TRIPPED ON OLR                                  | RESET DONE                                                        | 08:20:00 | 08:25:00 |                                                       |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 26/05/2026

Incharge(s): G Eswara Rao

Shift: A

| Sl No | Area | Equipment       | Problem                           | Action           | From     | To       | Remarks |
|-------|------|-----------------|-----------------------------------|------------------|----------|----------|---------|
| 10    | CHP  | SCR 10 ON CC105 | LT NOT TAKING PLACE/TENSION ACTED | TENSION RELEASED | 09:55:00 | 10:10:00 |         |
| 11    | WT   | OT 3            | DRIVE 1 TRIPPED ON ENCODER FAULT  | RESET DONE       | 13:35:00 | 13:40:00 |         |