



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 15/08/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CR-3A	Power cable found hanging	Dressing done properly and terminations checked and tightened	15:25:00	16:55:00	
2	OHP	WOBR on CO-6A	B/W not running	Checked and electrical side no problem found	14:20:00	15:15:00	Hydraulic motor problem suspected by mechanical
3	OHP	WOBR on CO-26	Reported Lt not taking place	PCRD cable fell down due to mechanical gearbox problem	17:00:00	17:30:00	Drum tied and loop given
4	OHP	CO-25	Reported tripped	OLR acted.Reset done	21:05:00	21:15:00	
5	CHP	CC-31 SCR-1	LT not taking place	Drive tripped.Reset done(3 times)	16:10:00	21:30:00	
6	CHP	Cc-125	CS acted	Sensor cleaned and tested okay	19:35:00	19:50:00	
7	CHP	Cc-54	Reported tripped	OLR acted.Reset done	21:20:00	21:30:00	
8	WT	OT-3	Reported tripped	D-1 tripped on encoder fault.Reset done	16:30:00	16:35:00	
9	WT	OP-5	Reported not moving	D2 tripped.Reset done	19:55:00	20:10:00	