



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/10/2026

Incharge(s): M Kailash

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RSCO-6A	OLR acted	Reset done	07:35:00	07:45:00	
2	OHP	BRC ON CO-30	CT not working. Drive tripped	Reset done	08:15:00	08:30:00	
3	OHP	CO-29	OLR acted	Reset done	08:30:00	08:40:00	
4	OHP	CO-13A	OLR acted	Reset done	08:38:00	08:45:00	
5	OHP	BRC ON CO-30	Boom conveyor not running. OLR acted	Reset done	09:35:00	09:45:00	
6	OHP	WOBR ON CO-6A	Interlock cage signal missing. Found ZSS structure bolt missing.	Temporarily made OK. Informed to General shift	10:15:00	10:40:00	
7	CHP	CC-26A	BRS is acting frequently due to belt pieces	Bypassed upto shift end as per operation request	09:40:00	09:50:00	
8	CHP	SCR-8 ON CC-106	Bucket wheel pump not starting. Found charge pressure healthy not coming.	Bypassed and made OK. Informed to mechanical.	10:20:00	10:40:00	In bypass
9	CHP	SCR-2 ON CC-33	LT not working. Drive tripped	Reset done	08:20:00	08:30:00	
10	CHP	SCR-3 ON CC-37	LT not working	Motor MPCB tripped. Reset done	11:50:00	12:00:00	
11	CHP	CC-52	Feeding conveyor tripped on overload	Reset done	07:30:00	14:00:00	7 times
12	CHP	CC-51	Feeding conveyor stopped	Reset done	10:00:00	13:40:00	3 times