



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/10/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO-29	Luff up not taking place	Oil level low	07:10:00	07:30:00	Informed to mechanical
2	OHP	CO-33M	Reported tripped	OLR acted.Reset done	11:50:00	11:55:00	
3	CHP	CC-51A	Reported tripped	OLR acted.Reset done(2 times)	08:45:00	09:00:00	
4	CHP	SCR-7 on CC-40	B/C not running	Communication problem.ZSS kept in line and tested okay	11:10:00	12:00:00	
5	CHP	SCR-6 on CC-38	B/C not running	Discharge chute CJD acted due to jamming	12:05:00	12:20:00	Informed to operation
6	CHP	CO-25,26,27	BRS acted	Fuse blwon at I/O rack.Replaced and tested okay	10:40:00	11:15:00	
7	WT	CP-2	Reported not moving	D-1 tripped due to brake binding	11:35:00	12:00:00	Informed to operation