वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 24/10/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on co 22	all drive not working,control mcb tripped	made it on	22:45:00	23:00:00	
2	OHP	rsco 6A(c)	olr acted	reset	22:54:00	23:00:00	
3	OHP	co 26	olr acted	reset	00:10:00	00:20:00	
4	OHP	CO 34	BRS and emergency acted,cable got cut and earthed b/w CJB to near motor,fuse blown	fuse replaced,cable checked from common cjb to BRS CJB ,brs bypassed in i/o rack	23:50:00	00:40:00	cable to be changed
5	CHP	CC 52	mpd acted	reset	04:40:00	04:45:00	
6	CHP	CC 15	olr acted	reset	23:10:00	23:15:00	3 times
7	CHP	CC 35 stk2	LT not working,m5 tripped	made it on	01:15:00	01:25:00	
8	CHP	CC 31	motor tripped due to olr	reset	01:20:00	01:25:00	
9	CHP	CC 104 scr 9	luff not working,pump is in off	made it on	02:30:00	02:40:00	
10	WT	CP 4	rev not moving,RLS acted	released RLS	23:00:00	23:10:00	
11	WT	CP 4	FWD not moving,FWD LS acted,LS problem	F LS bypassed in cjb	01:30:00	01:45:00	FLS to be changed