वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 13/10/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	tbs on con 20	LT not working,drive tripped	reset	15:10:00	15:20:00	2 times
2	OHP	BRC on co 31	CT not working,drive tripped in Oh2	reset	18:00:00	18:15:00	panel fan not working
3	OHP	WOBR on Co 29	LT not working,OT acted	Ot released	18:30:00	18:40:00	
4	CHP	CC 32 scr5	b/c not running,c/s problem	c/s nut and bolt replaced	14:00:00	14:30:00	
5	CHP	CC 106 scr8	Lt not working,control mcb tripped	made on	20:25:00	20:40:00	
6	CHP	CC 31	yard motor tripped in o/l	reset	19:40:00	19:50:00	
7	CHP	CC 32 scr2	LT not working	wrong complaint	20:00:00	20:15:00	
8	CHP	CC 54	mpd tripped	reset	19:15:00	19:20:00	5 times
9	CHP	CC 54	stopped in ZSS fault,due to overload	informed operation	17:33:00	17:43:00	
10	CHP	CC 52	mpd tripped	reset	19:15:00	19:20:00	
11	WT	CC 2	ZSS acted, probe problem loose connection	bypass in program 5 wagon tippled than kept in ckt,probe connected in module	20:30:00	20:40:00	