



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 09/09/2026

Incharge(s): Saurabh Kumar Yadav

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	wobr on co 29	LT not working,OT acted	Ot released	22:20:00	22:35:00	
2	OHP	co 34	OLr acted	reset	03:00:00	03:05:00	
3	OHP	co 47	zss acted	checked and found cage and probe working ok,wrong compliant	03:15:00	03:30:00	
4	OHP	RSCO 6A(c)	tripped due to track jamming	reset	04:25:00	04:30:00	
5	CHP	cc 58	tripped in curt sp fault	reset	00:35:00	00:50:00	
6	CHP	CC 131	motor tripped in olr	reset	02:50:00	03:00:00	
7	CHP	CC 28	FG mpcb tripped	made it on	23:15:00	23:25:00	
8	CHP	CC 29 on 33 position bit	not coming	bypass	23:45:00	23:50:00	
9	CHP	CC 40 SCr7	b/c not working,mpd acted	reset	01:10:00	01:18:00	