वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 01/11/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-26	Reported tripped	OLR acted.Reset done	08:45:00 13:30:00	09:00:00 13:35:00	
2	OHP	WOBR on CO-6A	Cabin adjustment not taking place	PB contact loose at operator cabin.Tightened and tested okay	09:05:00	09:25:00	
3	OHP	WOBR on CO-29	LT not taking place	Wrong complaint	10:00:00	10:10:00	
4	OHP	TBS on CO-20	Luffing not taking place	OLR acted.Reset done	08:00:00	08:15:00	
5	CHP	Cc-54	Reported tripped	OLR acted.Reset done	08:00:00	09:00:00	
6	CHP	SCR-9 on CC-104	Luffing not taking place	PLC glass relay to output TB wire loose.Tightened and tested okay	09:35:00	09:50:00	
7	CHP	SCR-7 on CC-40	Luffing not taking place	OLR acted.Reset done	11:35:00	11:45:00	
8	CHP	CC-215	Reported tripped	OLR acted.Reset done	09:35:00	09:45:00	
9	WT	OP-4	Reported not moving	Breaker tripped.Checked and found bottom pad C clamp damaged.Replaced and tested okay	10:15:00	10:45:00	
10	WT	OP-7	Reported not moving	Reverse limit switch in acted condition.Released and tested okay	06:30:00	06:45:00	
11	WT	OC-1A,OAF-1A,OAF-2A	Showing in local	PLC power recycled at LC-9 and tested okay	12:15:00	12:30:00	
12	WT	OT-5	Reported not rotating	Checked and found LS-3 limit not healthy.Bypassed through scada and tested okay	12:20:00	12:35:00	LS-3 limit to be checked

वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 01/11/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	IOSA	OC-27A	Reported healthy stop	Checked and found no problem.Made to run and found okay	12:52:00	13:00:00	