



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 03/07/2026

Incharge(s): M Kailash, K SANKARA RAO

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR-25	LT not healthy. Found M1 overload acted	Reset done	09:55:00	10:10:00	
2	CHP	cc-52	Tripped. Found MPR tripped	Reset done	08:00:00	08:05:00	
3	CHP	cc-58	Not Healthy. Checked local control stations and found element loose in push button station near walkway. Made OK	connection tightened and made ok	12:00:00	12:30:00	
4	CHP	cc-203	Overload acted	reset done	08:45:00	08:55:00	
5	CHP	cc-201	ZSS bypassed in c.shift	ZSS kept in circuit and tested in LOCAL	11:00:00	11:20:00	
6	WT	oc-1A	Not starting. Checked and found healthy	OCR-2 operator reset done and started	13:00:00	13:00:00	
7	WT	sco-1A	ZSS acting.	Probe adjustment done	11:00:00	11:15:00	