



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/04/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-62	Reported CJD malfunctioning	Instrumentation attended and sensitivity adjusted and tested okay	18:05:00	18:20:00	
2	OHP	CO-26	Reported tripped	OLR acted due to over material on belt and offcentering.Reset done	15:50:00 16:35:00 17:15:00 19:10:00 20:50:00	16:05:00 16:45:00 17:25:00 19:20:00 20:55:00	
3	OHP	CO-84	Reported BRS not getting reset	BRS sensors cleaned and adjusted checked and tested okay	21:10:00	21:30:00	
4	CHP	CC-201	Reported tripped	OLR acted.Reset done	18:20:00	18:30:00	
5	CHP	CC-33 SCR-5	LT not taking place	Drive tripped.Reset done	21:15:00	21:25:00	
6	CHP	Cc-29	Reported tripped	OLR acted.Reset done	21:15:00	21:20:00	
7	CHP	Cc-51	MPD tripped	Reset done	19:42:00	19:52:00	
8	CHP	CC-52	Reported tripped	Reset done	21:43:00	21:45:00	
9	WT	CT-1	Reported tripped	OLR acted.Reset done	18:20:00	18:30:00	
10	WT	CT-2	Inhaul not working	Control tripped due to earth fault at PB station.Tapped and tested okay	16:30:00	17:00:00	
11	WT	OP-7	Reported not moving	LS-2 bypassed and tested okay	19:25:00	19:30:00	