



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 08/08/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO-34	B/W-1 not running	Checked and found fluid coupling oil leakage.	23:15:00	23:30:00	Informed to mechanical
2	OHP	TBS on CO-5A	Reported all drives not working	E-stop pressed in operator cabin. Released and control made on and tested okay	03:05:00	03:25:00	
3	OHP	CO-26	Reported tripped	OLR acted. Reset done	03:40:00 05:37:00	03:50:00 05:45:00	
4	OHP	WOBR on CO-6A	B/W not running	Charge pressure acted.	04:42:00	05:20:00	Informed to mechanical
5	CHP	CC-40	Reported tripping	MPR tripping on under current fault. In settings made it off and tested okay. Currents found normal	00:40:00	01:30:00	
6	CHP	CC-40 SCR-7	B/C not running	MPD tripped. Reset done	04:55:00	05:10:00	
7	CHP	CC-54	Reported tripped	OLR acted. Reset done	00:05:00	00:10:00	
8	WT	OAF-2A	Reported not running	Drive tripped. Reset done	22:35:00	22:40:00	
9	WT	OT-3	Reported tripped	D-1 tripped on encoder 43 fault fault. Reset done	00:15:00	00:20:00	
10	WT	AF-4	Reported not healthy	Control MCB off. Made on	00:10:00	00:15:00	