



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 17/05/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 26	olr acted	reset	14:00:00	14:10:00	3 times
2	OHP	TBS on CO 5A	LT not working,pcrd OT acted	OT released	16:40:00	17:00:00	
3	OHP	BRC on CO 28	b/w 2 not moving,back plate stucked in bucket	informed mechanical and operation	17:00:00	17:15:00	
4	OHP	CO 35	olr acted	reset	20:50:00	21:00:00	
5	OHP	rsco 10 a (c)	power and control is in off	made it on	17:05:00	17:15:00	
6	CHP	cc 51	mpd acted	reset	19:01:00	19:07:00	2 times
7	CHP	CC 54	mpd tripped	reset	19:10:00	19:20:00	
8	CHP	VF 3	OLR acted	reset	21:15:00	21:25:00	
9	CHP	CC 29	ZSS ACTED, CAGE STUCKED	CAGE MADE FREE	18:20:00	18:30:00	
10	WT	CP2	no movement,d6 stator contactor not pickedup	casacade timer made zero,coil continuity ok, coil having low value resistance, contactor to be replaced (3TF54)	20:00:00	20:10:00	no delay memeo timing change,due to brake binding