



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/05/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 29 wobr	luffing not working,olr acted	reset	07:00:00	07:15:00	
2	OHP	TBS on co 5A	LT not working,OT acted	OT released	08:55:00	09:10:00	
3	OHP	CR1	not healthy, tripped in OC, 1 no of HT fuse blown	power made off, megger done from cable and near motor TB all ok, fuse replaced and charged	09:00:00	11:10:00	
4	OHP	TT3	bpc 1 bit missing, bypass wire loose connection	tightening done	10:50:00	11:00:00	
5	CHP	CC 58	mpr tripped	reset	06:45:00	07:00:00	
6	CHP	CC 113, 113A	not healthy, cm 36 fdr tripped	made on	12:45:00	13:00:00	
7	CHP	CC 32 S3	LT not working, drive tripped	reset	08:30:00	08:40:00	
8	CHP	CC 36 s1	b/c not running, slew 30 degree problem	slew done than ok	08:50:00	09:00:00	
9	CHP	CC 43	olr acted	reset	11:15:00	11:25:00	
10	CHP	cc 44	olr acted	reset	12:50:00	12:55:00	
11	CHP	CC 203	olr acted	reset	06:30:00	06:40:00	